

## SB Issuer/TC holder

**Company name:** Pipistrel Vertical Solutions d.o.o.  
**Address:** Vipavska cesta 2, 5270 Ajdovščina, Slovenia  
**Website:** [www.pipistrel-aircraft.com](http://www.pipistrel-aircraft.com)  
**Contact:** +38653658160  
**Type:** ALPHA Trainer  
**Model** ALPHA Trainer

| FUNCTION:              | NAME: | DIGITAL SIGNATURE WITH TIMESTAMP: |
|------------------------|-------|-----------------------------------|
| Verified and approved: | HOA   |                                   |

This document is verified and approved under the authority of DOA-No.: SLO.DOA.002

**List of issues and alterations**

| <b>ISSUE</b> | <b>REASON FOR ALTERATION</b> | <b>PAGES AFFECTED</b> | <b>DATE OF ISSUE</b> |
|--------------|------------------------------|-----------------------|----------------------|
| <b>A00</b>   | Initial issue                | all                   | 19.11.2019           |

**SB Name: Fuel pump switch retrofit****Category:** Information / Recommended / Mandatory**Subject:** Electrical installation modification that allows independent activation and deactivation of auxiliary electric fuel pump via dedicated switch.**Affected Aircraft:** All ALPHA Trainer LSA aircraft up to and including s/n 958 AT 912 LSA, that do not already have a dedicated fuel pump switch installed in the switch panel.**Date of issue** 19.11.2019**Date of effect** 19.11.2019**Time of Compliance:** N/A**Reason:** Possibility of using of auxiliary fuel pump only when needed and easier detection of primary mechanical fuel pump failure.**Actions: Part 1: Retrofit implementation**

Order fuel pump switch retrofit kit P/N 1159621 and perform instructions in [1].

**Part 2: Reporting compliance**

Report compliance with this SB by scanning the QR code or clicking on the link below and filling out/submitting Pipistrel's service document compliance form.

<https://www.pipistrel-aircraft.com/support/other-service-document-compliance-form/>



**Documents:** [1] PI-160-91-60-101 Fuel pump switch retrofit

NOTE: A printed version of [1] is included in the fuel pump switch retrofit kit.

**Personnel and site requirements:** The actions required by this SB can be performed by the owner, who is also a licensed pilot.

**Required Material:** The following kit can be ordered through your local Pipistrel dealer.

Fuel pump switch retrofit kit (p/n 1159621)

**Mass and Balance:** N/A

**Required Records:** Compliance with this service bulletin must be confirmed in the aircraft records.

**Remarks:** If additional assistance is needed with this procedure, contact the Pipistrel via email: [support@pipistrel.si](mailto:support@pipistrel.si)

This page is intentionally left blank.

**END OF SERVICE BULLETIN**