



RECREATIONAL AVIATION AUSTRALIA INC

Date: 17 February 2011

RECREATIONAL AIRCRAFT AIRWORTHINESS NOTICE

AIRWORTHINESS NOTICE IDENTIFICATION NUMBER: **RA-Aus AN17022011-1**
(issue 1)

COMPUSORY COMPLIANCE WITH JABIRU JSB029-1 (J170 AIRCRAFT

To: All owners and operators of Jabiru J170 (all models including LSA) Aircraft.

Background: On 20 January 2011 Jabiru issued **Service Bulletin JSB029-1** for all Jabiru J170 aircraft. (A copy can be downloaded from the RA-Aus web site) (<http://www.raa.asn.au/airworthiness/index.html#jabiru>)

Discussion: Failure to comply with the compulsory Jabiru Service Bulletin – JSB029-1 may adversely affect the handling characteristics of the affected aircraft.

Action Required:

Complete the requirements of Jabiru Service Bulletin JSB029-1 within the compliance periods specified in this document.

At each periodic inspection: Inspect the affected areas.

Recommended Further Action: Compliance with JSB029-1 is a finishing action

Reports and Recording: Compliance is to be recorded in the aircraft log book citing **RA-Aus AN17022011-1 (Issue 1)** and **JSB029-1**, any deficits found during compliance are to be reported to the RA-Aus office and Jabiru Aircraft Pty Ltd within 7 days of detection.

Technical Manager

**Defect Reporting is one of the primary ways we have in ensuring continued safety
in our operations.**